This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




Figure 1




Figure 2




Figure 3




Figure 3 (continued)




Figure 3 (continued)




Figure 4

```
**EQUIPMENT CHECK**

(1=OK 0=Failed)

^Horn

194 _____Brakes

196 ____Steering

198 ____Direction Controls

200 ___Tires OK

201 ___Amy Damage
```

Figure 5




Figure 6




Figure 7




Figure 8




Figure 9




Figure 10

UNRECOGNIZED OBJECT

The Chosen Object is
Not a Loadable
Object
in any known Load

Figure 11




Figure 12




Figure 13




Figure 14

==




Figure 15




Figure 16




Figure 17




Figure 18




Figure 19

DOOR STATUS		
Door:	A-12	292
Load:	1234-	290
Load Status:	Opened-	294
Trailer:	111111-	296
ENTER = Load Summary CLEAR to Cancel		

Figure 20




Figure 21




Figure 22




Figure 23




Figure 24